

$$\dot{E} \propto F^2 \propto \dot{n}$$










类型	CT	PT
编号	0002	
励磁 变比极性 交流耐压 一次通流 数据查询 退磁		
日期: 2015-07-23 15:06:15		

类型	PT	CT
编号	0002	
励磁 变比极性 交流耐压 数据查询		








类型	CT	PT
编号	0002	
励磁电压	1000 V	
励磁电流	0.075 A	
交流耐压		
一次匝数		
数据查询		
校准		
开始	退出	校准
日期: 2012/01/01		




I (A)	U (V)	退出
0.002	0.5	
0.005	5.8	
0.008	16.5	
0.010	25.0	
0.015	49.0	
0.018	60.0	
0.020	70.0	

类型	CT	PT	
编号	0002	2012/01/01	打印








类型	CT		PT
编号	0002		
一次	___ A	二次	___ A
变比	-		




励磁
变比极性
交流耐压


一次: ___ A 二次: ___ A

开始

退磁








类型	PT	CT
编号	0002	
额定二次: V		
开始退出		
日期: 2024-07-22		


励磁
变比极性
交流耐压
数据查询
退出



类型	PT		CT
编号	0002		
设定电压	1000		v
实际			





类型	CT	PT		
编号	0002			
			励磁	
			变比极性	
退出				
日期 2012/02/10 15:06:15				











类型	==CT==	PT
编号	0002	2012/01/01
		打印
		励磁数据
		保存
		误差曲线
		退出
		打印设定

检查空开

类型	==CT==	PT
编号	0002	2012/01/01
		打印
		励磁数据
		保存
		误差曲线
		退出
		打印设定

检查接线

0 0.075

U = 28 V I = 0.075 A

类型	==CT==	PT
编号	0002	
一次	A	二次 A
变比		
检查空开/一次接线		数据查询
A 二次: A		退磁
打印 保存 退出		极性
2/02/10 15:06:15		一次: 开始
		日期: 201

类型	==CT==	PT
变比极性		
一次	A	一次 A
变比		
极性		
一次: A	二次: A	一次通流
开始		数据查询
日期: 2012/02/10 15:06:15		退磁